



## Mallory Distributor for Land Rover 3.9 Engines

Land Rover no longer makes a distributor for the 3.9 Discovery I and Range Rover Classic. Hard work at trying to locate an alternative, our purchasing department has found the perfect aftermarket solution. Get the same performance, at an aftermarket price.

### Product Description

This is a new Mallory Distributor and will fit the above applications. This product requires a ballast resistor, Mallory part# 700, to be installed with it.

### Features & Benefits

- No longer available through the dealership
- High quality part that exceeds OE specifications
- Includes new rotor, cap, and electronics
- Detailed Instructions and wiring diagram included
- Easy to install

### Part# & Application

ERR5209A - Discovery I 1994-1995 | Range Rover Classic 1992-1993